

≡PILATUS≡
PC12
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
 NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
Chapter 04 - Airworthiness Limitations			
04-001	25-Mar-97	Conversion of the PC-12 to a PC-12/45 Variant	19
04-002 Rev. 3	15-Jun-04	Canadian-Registration of the PC-12 and PC-12/45	27
04-003 Rev. 1	29-Jun-00	Brazilian Registration of the PC-12 and PC-12/45 Aircraft (Available on Request)	40
04-004	04-Dec-97	Argentinian Registration of the PC-12 and PC-12/45 Aircraft (Available on Request)	42
04-005 Rev. 1	12-Sep-01	Airworthiness Limitations - - French Registration of the PC-12	107
04-006 Rev. 1	18-Jun-01	Airworthiness Limitations - PC-12 and PC-12/45 Aircraft - Netherlands Certification (Available on request)	114
04-007	20-Aug-04	Airworthiness Limitations - PC-12 and PC-12/45 Aircraft - CIS Certification (Available on request)	189
Chapter 11 - Placards and Markings			
11-001	24-Feb-95	Take-off/Landing Weight and Speed Placard.	3
11-002	20-Nov-01	Placards and Markings - Interior Placards - Flight Compartment Flap Placard - Replacement	146
11-003 #	16-Sep-02	Placards and Markings - Interior Placards - Incorrect Placard in the Flight Compartment	160
Chapter 21 - Air Conditioning			
21-001 Rev. 1	03-Mar-97	Pressure Control System Installation - Solenoid Valve.	9
21-002	17-Feb-98	Revised Ducting for the Auxiliary Heating System Air Distribution	44
21-003 Rev. 1	21-Jul-00	Air Conditioning - General - Modification of Auxiliary Piping and Installation of Improved TCV	45
21-004	11-Sep-98	Installation of Additional Foot Warmers for the Pilot and Copilot	48
21-005	08-Dec-99	Environmental Control System - Installation of Environmental Control System Vibration Isolators	106
21-006 Rev. A	30-Jun-00	Air Conditioning - General - Installation of a Cover Over the ECS Temperature Control Valve	113
21-007	19-Aug-04	Air Conditioning - Temperature Control - Change the Cable Routing	188
Chapter 22 - Auto Flight			
22-001	15-Dec-94	Replace EPROM IC (I236) in the Flight Control System.	2
22-002	24-Oct-97	Modification of Angle of Attack (AOA) Transmitter Mountings	25
22-003 #	24-Jun-99	Adjustment of Output Torque of Stick Pusher Actuator and Capstan Clutch	67
22-004	21-Dec-04	Auto Flight - Autopilot - Pitch Actuator - Replacement	191
Chapter 23 - Communications			
23-001	24-Oct-97	Installation of Improved Static Dischargers	43

≡PILATUS≡
PCI2
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
 NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
23-002	04-Sep-00	Communications - VHF COMM - Replacement of VHF/COMM Radios KX155 or KX165 with Radios KX155A or KX165A (VHF/COMM - 8.33 KHz Channel Spacing)	117
23-003	17-Nov-00	Communications - VHF/COMM - Replacement of VHF/COMM Radios KX155 or KX165 with Radios KX155A or KX165A (VHF/COMM - 8.33 KHz Channel Spacing)	125
23-004	08-May-03	Communications - Audio Integrating - Introduction of a Microphone Selector Switch and Connection for the Oxygen Mask Microphone	168
Chapter 24 - Electrical Power			
24-001	27-Sep-96	Replacement of Second Generator Drive Housing	13
24-002 # Rev. 1	20-Sep-96	Re-routing of Power-return Cables of the Starter-Generator & Generator 2	6
24-003 # Rev. 1	18-Sep-96	Rewiring of the Automatic Disconnect Circuit for the Non-essential Bus & Check of the Navigation Converter (KN 40) for Correct Wiring.	7
24-004	03-Jun-97	Replacement of Starter Delay Relay	31
24-005	24-Oct-97	CB211 Bus Tie GEN 1 Uncontrolled Opening	36
24-006	12-Feb-98	Installation of a Cable Tie Attachment at Frame 40	59
24-007	04-Feb-98	Installation of Two Circuit Breakers at Frame 19	56
24-008 Rev. 2	30-Aug-02	Electrical Power - External Power - Installation of an External Power Control Unit	70
24-009 #	23-Sep-98	Electrical Power - DC Generation - Installation of a Cut-off Relay	73
24-010 Rev. 1	06-Oct-03	Electrical Power - DC Generation - Electrical Power - DC Generation - Replacement of the Generator 2	76
24-011	28-Jun-01	Electrical Power - DC Generator - Generator 1 Amp Indication System - Installation	138
24-012 #	19-Feb-99	Electrical Power - General - Modification of the GEN2 Excitation	87
24-013	23-Aug-99	Electrical Power - Battery - Check and/or Replacement of the Battery Connector	98
24-014 #	27-Oct-99	Electrical Power - General - Replace the Suppression Filter (A250)	102
24-015	09-Aug-00	Electrical Power - General - Installation of a Protection Cover	115
24-016 Rev. 1	15-Nov-01	Electrical Power - Brush Holder in Second Generator - Brush Holder Replacement	118
24-017 Rev. 1	14-Mar-02	Electrical Power - DC Generation - Replacement of Nickel Cadmium Batteries with Lead Acid Batteries	143
24-019 Rev. 1	06-Jun-03	Electrical Power - DC Generation System - Generator 2 - Generator 2 Control Unit - Replacement	156
24-020	23-Oct-03	Electrical Power - DC Electrical Load Distribution - Change LDG LIGHT RH Circuit-Breaker from NON ESSENTIAL BUS to GENERATOR BUS	177
24-021 #	06-Jun-03	Electrical Power - DC Generation - Gen 1 Ground Sensing Lead	171
24-022 #	13-Jun-03	Electrical Power - DC Power - Replacement of the Generator Control Unit for aircraft with the Second Battery Option	172

≡PILATUS≡
PCI2
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
Chapter 25 - Equipment and Furnishings			
25-001	24-Sep-97	Modification of the Aircraft Crew Seats Adjustment Mechanism	32
25-002 Rev. 1	13-Oct-98	Installation of Supplementary Battery and Engine Heating Systems	28
25-003 Rev. 1	07-Apr-98	HIC Modifications to the Executive Cabin Layout	30
25-004	24-Oct-97	Executive Toilet Wiring Modification	41
25-005 Rev. 1	27-Feb-98	Installation of Passenger Seat Luggage Restraint Bar	55
25-006 #	07-Apr-98	HIC Modifications to the Corporate Commuter Cabin Layout	63
25-008	06-Jul-98	Equipment/Furnishings - Insulation - Passenger Door Thermal Blanket	68
25-009	17-Jun-98	Equipment/Furnishings - Flight Compartment - Crew Seat Lap Belt	69
25-010	05-Mar-99	Equipment/Furnishings - Passenger Compartment - New Baggage Net Installation	84
25-012 Rev. 1	24-Nov-00	Equipment and Furnishings - Passenger Cabin - Equipment and Furnishings - Passenger Cabin - Installation of New Insulation	88
25-013 Rev. 1	05-Apr-00	Equipment and Furnishings - Cabin Underfloor - Insulation and Drainage	89
25-014	20-Apr-99	Equipment and Furnishings - Passenger Compartment - Installation of a 3-Bench Seat to the Executive Model	92
25-015	27-Apr-99	Equipment and Furnishings - Flight Compartment - Modification of the Crew Seats	93
25-016 Rev. 1	27-Sep-00	Equipment and Furnishings - Passenger Compartment - Installation of Interior Code Placard and Identification of Baggage Nets	103
25-017 Rev. A	18-Apr-01	Equipment and Furnishings - Passenger Compartment - Installation of Cargo Hold Curtain	132
25-019	27-Sep-00	Equipment and Furnishings - Passenger Compartment - Baggage Nets Limitations	121
25-020	26-Feb-01	Equipment and Furnishings - Emergency Equipment - Installation of the ELT 910 Remote Control/Monitor panel	130
25-021	14-Mar-02	Equipment and Furnishings - Emergency Equipment - Introduction of the Kannad 406AF Emergency Locator Transmitter as a Replacement for the Kannad 121 AF Emergency Locator Transmitter	148
25-022	01-Feb-02	Equipment and Furnishings - Emergency Equipment - Introduction of the Kannad 406 AF Emergency Locator Transmitter as a Replacement for the Narco 910 Emergency Locator Transmitter (Superseded by SB 25-028)	147
25-023 #	05-Jul-01	Equipment and Furnishings - Insulation - Fire-wall Insulation - Apply Adhesive Tape	139
25-024	15-Aug-02	Equipment and Furnishings - Emergency Equipment - Introduction of New Emergency-Locator-Transmitter Control Panel (Superseded by SB 25-027)	155
25-025 #	27-Sep-02	Equipment and Furnishings - Passenger Compartment - Executive Seat- Inspection of Part Number and Pedestal Leg Assembly	161
25-026	07-Mar-03	Equipment and Furnishings - Flight Compartment - Pilots Relief Tube - Installation	166

≡PILATUS≡
PCI2
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
25-027 Rev. 1	21-Apr-04	Equipment and Furnishings - Emergency Equipment - Emergency-locator-transmitter control panel - Replacement	179
25-028	08-Jan-04	Equipment and Furnishings - Emergency Equipment - Emergency-locator-transmitter and control panel - Replacement	180
25-029	17-Feb-04	Equipment and Furnishings - Emergency Equipment - Emergency-locator-transmitter - Introduction of an optional dongle/smart connector	182
25-030	17-Feb-04	Equipment and Furnishings - Emergency Equipment - Introduction of an emergency-locator-transmitter GPS navigation interface - Installation	183
25-031 #	21-Jul-04	Equipment and Furnishings - Flight Compartment - Crew Seats - Inspection of the Crew Seat Back-Rest	185
Chapter 27 - Flight Controls			
27-001 #	25-Mar-97	Modification of Aileron Tie-rod Assembly	26
27-002	03-Jan-98	Modification of the Landing Flap Resolver System	37
27-003 #	08-Mar-99	Flight Controls - Flaps - Replacement of all Flap Flexible Drive Shafts	74
27-004 #	15-Sep-98	Flight Controls - Flaps - Remove the Alternate Flap System	75
27-005 #	18-Nov-98	Flight Controls - Flaps - Check of all Flap Actuators	79
27-006 Rev. 1	18-Jun-01	Flight Controls - Flaps - Flight Controls - Flaps - Installation of a New Flap Reset System	91
27-007 #	26-Jan-99	Flight Controls - Flaps - Control of Limited Service Life Flap Screw Actuators	85
27-008 # Rev. 2	13-Sep-00	Flap - General - Replacement of the FCWU and Modifications to the System	110
27-009	23-Sep-99	Flight controls - Flaps - Modification of the Flap Limit Micro-switches	100
27-010	31-Mar-00	Flight Controls - Aileron System - Modification of the Aileron Control Installation	111
27-011 # Rev. 1	26-Jan-01	Flight Controls - Flaps - Modification to the Control System Wiring	127
27-012 #	13-Sep-00	Flight Controls - Flaps - FCWU - Replacement	119
27-013 Rev. 1	19-Jan-05	Flight Controls - Flaps - PDU Replacement	133
27-014	29-Jun-01	Flight Controls - Flaps - Introduction of a New Flap-Motor Relay	137
27-015 # Rev. A	13-Nov-03	Flight Controls - Flaps - Replacement of Inboard and Outboard Flap Flexshafts	169
27-016	04-Feb-04	Flight Controls - Flaps - Power Drive Unit - Replacement (Limited Distribution Only)	181
Chapter 28 - Fuel			
28-001	22-Nov-96	Modification of the Fuel System - Install New Check Valves in Wings	17
28-002	19-Jul-96	Installation of a new Fuel Emergency Shut-off Lever	10
28-003 # Rev. 1	30-Sep-97	Modification of the Fuel Tank Inward Vent Valves	39
28-004 #	27-Mar-98	Fuel - Storage - Modification of the Fuel Filler Caps	64
28-005 #	04-May-98	Fuel - Storage - Modification of the Vent Valve System	65
28-006	04-May-98	Fuel - distribution - Modification of the Delivery Ejector Pumps	66

≡PILATUS≡
PCI2
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
28-007	09-Aug-99	Fuel - Distrubition - Replacement of the Fuel Filter O-ring Seals	99
28-008	19-Jun-01	Fuel - Distribution - Fuel Booster Pump - Inspection of Armature End Play	136
28-009 #	10-Aug-01	Fuel - Distribution - EDP - Torque Check of Relief valve Body Screws	140
28-010 #	16-Sep-02	Fuel - Distribution - Engine Driven Pump - Replacement Relief-Valve-Body Housing and Seals	158
28-011 # Rev. 1	11-Jul-03	Fuel - Distribution - Fuel Booster Pump - Damage to Wires During Installation	170
Chapter 29 - Hydraulic Power			
29-001 #	01-Jul-96	Modification of the Hydraulic Hand-pump Handle.	8
29-002	12-Aug-97	Cure for Oil Seepage from Shaft Seal of the Hydraulic Power Pack	34
29-003	02-Sep-97	Modification of the Hydraulic Service Selector Valve	35
Chapter 30 - Ice and Rain Protection			
30-001	20-Dec-95	Modification to the Anti-icing and De-icing Systems.	5
30-002 #	16-Sep-96	Replace the Propeller De-icing Controller (PDIC) (P/N: 968.29.13.223)	11
30-003	16-Sep-96	Replace the AOA Plate (Temperature) Controller (P/N: 975.44.21.417)	12
30-004	18-Sep-98	Ice and Rain Protection - Propeller De-icing - Installation of New Timer Unit and Brush Pack	71
30-005 #	24-Jun-99	Ice and Rain - Windshield - Modification of the Windshield Wires	95
30-006 #	22-May-00	Ice and Rain Protection - Modification to the Windshield De-ice System Wires and Circuit Breakers	112
30-007	06-Oct-03	Ice and Rain Protection - Windshield - Replacement of the Old Type Windshields with the New Type Windshields	176
30-008	21-Aug-03	Ice and Rain Protection - Pitot and Static - Pitot, Static and AOA De-Icing Sensor Check	173
30-009 #	25-Jan-05	Ice and Rain Protection - Windshield Deice System - Windshield Deice System Wiring - Inspection	192
Chapter 31 - Indicating/Recording systems			
31-002	12-Oct-00	Indicating/Recording systems - Instrument and Control Panels - Introduction of a New Glare Shield	122
31-003 #	27-Sep-02	Indicating/Recording systems - Instrument and Control Panels - Replacement of the Switch Caps on the Overhead Panel	162
31-004 Rev. A	05-Feb-03	Indicating/Recording systems - Central Warning Systems - Modification to the Central Advisory and Warning Control System	164
31-005	10-Feb-03	Indicating/Recording systems - Central Warning Systems - Replacement of Central-Advisory Computer Units CACU91 Series with CACU97-2	165
Chapter 32 - Landing Gear			
32-001	15-Dec-94	Nose Landing Gear - Crack Inspection of the Forged Main Fitting	1

≡PILATUS≡
PCI2
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
 NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
32-002 Rev. 1	05-Jan-96	Replacement of Brake Unit	4
32-003 Rev. 1	29-Sep-97	Main Landing Gear Attachment Spacer	33
32-004	18-Mar-98	Replace Brake Pedal Levers and Adjust the Mechanism	62
32-006	18-Dec-98	Landing Gear - Main Landing Gear - Axle Replacement	80
32-007	27-Aug-99	Landing Gear - General - Installation of Static Dischargers on the Main Landing Gears	96
32-008	14-Sep-99	Landing Gear - Nose Landing Gear - Modification to the Seals and Barrel Nut	101
32-009	12-Oct-00	Landing Gear - Main Landing Gear - Axle Replacement	123
32-010	27-Sep-00	Landing Gear - Nose Landing Gear (NLG) - Modification of the NLG Main Fitting	120
32-011	13-Nov-00	Landing Gear - Main Landing Gear - Introduction of New Shock-Absorber Attachment Nut	124
32-012 #	18-Oct-01	Landing Gear - Main Landing Gear - Main Landing Gear - Special Bolt Assembly - Replacement	144
32-013	26-Mar-02	Landing Gear - Wheels and Brakes - Brake Unit - Replace	150
32-014 # Rev. 1	13-May-03	Landing Gear - Nose Landing Gear (NLG) - Replacement of Drag Link Right-Hand	153
32-015 #	12-Sep-03	Landing Gear - Landing Gear - Landing Gear - Inspection and Replacement of Components	174
32-016 #	11-Mar-04	Landing Gear - Landing Gear - Landing Gear - Inspection and Replacement of Components	184
32-017 #	30-Aug-04	Landing Gear - Main Landing Gear - Actuator - Replacement	187
Chapter 33 - Lights			
33-001	03-Feb-99	Lights - Exterior - Recognition lights	81
33-002	15-Jan-99	Lights - Exterior - Red Anti-collision Beacons	82
33-003	25-Nov-99	Lights - Exterior - Installation of Logo Lights	97
33-004	10-May-99	Lights - Flight Compartment - Replacement of the Dimmer Unit	90
33-005	02-Feb-01	Lights - Exterior - Introduction of New Wing-Tip Anti-Collision Lights and Power Supply Units (PSU)	128
33-006 Rev. 1	14-Feb-03	Lights - Passenger Compartment Lights - Cabin Flood lights - Install New Diode	157
33-007	12-Aug-02	Lights - Passenger Compartment Lights - Baggage Bay and Cargo Door Light - Install	154
33-008	28-Nov-02	Lights - Passenger Compartment Lights - Cabin Flood Lights - Remove Diode	163
33-009	17-Apr-03	Lights - Exterior - Introduction of Dual Navigation Lights	167
Chapter 34 - Navigation			
34-002	10-Oct-96	Installation of a Second AHRS (AHRS2)	18
34-003	17-Oct-96	Modification on LITEF LCR-92 AHRS	14

≡PILATUS≡
PCI2
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
34-004	01-Apr-97	Installation of the Yaw Rate Gyro (KRG 332)	22
34-005	03-Jun-97	Installation of the Radar Altimeter (KRA 405)	23
34-006 #	03-Sep-98	Navigation - Attitude & Direction - Stand-by Magnetic Compass Swing	72
34-007	28-Mar-00	Navigation - Flight Environment Data - Pitot Head Electrical Heating Cables - Replacement	109
34-010	21-Jul-04	Navigation - Dependant Position Determining - Dual Mode S Transponder CTX330D - Installation - Limited Issue Only	186
34-012	18-Nov-04	Navigation - Dependant Position Determining - Dual Mode S Transponder GTX330D - Modification	190
Chapter 35 - Oxygen			
35-001 Rev. 1	23-Jan-03	Oxygen - General - Introduction of Oxygen Shut-off Valve System	54
35-002 #	19-Dec-00	Oxygen - Passenger Oxygen - Improved Distribution of Oxygen to Occupants of Three Bench Seat	126
35-003	17-Sep-01	Oxygen - Passenger - Installation of an Oxygen Mask in the Lavatory	142
35-004 #	19-Dec-03	Oxygen - Passenger Oxygen - Oxygen Pipes - Change Routing Positions	178
Chapter 52 - Doors			
52-001 Rev. 1	13-Oct-98	Install improved Emergency Exit Seal, Locking Mechanism and Installation Doors - Emergency Exit - Locking Mechanism, Adjustment Fitting and Insulation	47
52-002	10-Oct-97	Installation of New Door Locks	46
52-003	29-Jan-99	Doors - Emergency Exit - Installation of an Improved Emergency Exit Seal	83
52-004 # Rev. 1	10-Sep-01	Doors - Cargo Door - Cargo Door Frames - Inspection and Installation of Reinforcing Plates	134
52-005	09-May-01	Doors - Cargo Door - Modification of the Cargo Door	135
52-006	22-Apr-02	Doors - Passenger/Crew - Attachment of Door-Support Brackets	151
Chapter 53 - Fuselage			
53-001	06-Feb-98	Modification of the Cargo Door Support on the Fuselage	49
53-002	12-Feb-98	Replacement of the Passenger Door Bearing Support on the Fuselage	60
53-003 # Rev. 1	26-Jul-02	Fuselage - Rear Fuselage - Rear Pressure Bulkhead - Inspection and Repair	152
Chapter 55 - Stabilizers			
55-001 #	08-Nov-96	Elevator - Inspection and Repair	15
Chapter 56 - Windows			
56-001	19-Jan-98	Modification of the DV-Window	51
56-002 Rev. 1	23-Jun-04	Windows - Flight Compartment - D.V. Window - Replacement	129

≡PILATUS≡
PCI2
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
 NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
Chapter 57 - Wings			
57-001	28-Feb-97	Electrical Bonding of Fuel Tank Access Covers	24
57-002	20-Mar-98	Replace the Inboard Flap Fairing Support Brackets	61
57-003 Rev. 1	01-Oct-98	Installation of New Wing Tips (Tiplets)	58
57-004 #	11-Jun-99	Modification of the Flap Inboard Attachment Fittings	94
57-005	25-Mar-02	Wings - Trailing Edge - Inboard-Flap Support-Arm Attachment-Brackets - Replacement Bolts	149
Chapter 71 - Powerplant			
71-001	15-Dec-97	Modification of the Guide Vane Assembly	52
71-002	13-Jan-98	Modification of the Engine Fire Wire	50
71-003	08-Dec-99	Power Plant - Air Intake - Modification of the Air Intake De-icing Lip	105
71-004 #	22-Dec-99	Powerplant - Torque Oil Pressure and Py Pressure Pipes - Inspection (and Adjustment and replacement if Necessary)	108
71-005 Rev. 1	21-Aug-03	Powerplant - PowerPlant - Torque Oil Pressure Pipe and Hose Assemblies - Replacement	131
71-006	16-Sep-02	Powerplant - Stripdown/Build-up - Electrical Harness - Change the Routing	159
Chapter 72 - Engine			
72-001	26-Feb-97	Engine Torque Limiter Adjustment	20
72-002	28-Apr-97	Change the FCU (Ref. P&WC SB 14254) and Set the Engine Parameters.	29
Chapter 73 - Engine Fuel and Control			
73-001	20-Feb-97	Replacement of the FCU and Re-rigging of Engine Controls	21
Chapter 74 - Ignition			
74-001	29-Jan-98	Re-routing of the Ignition Cables (Ref. P&WC SB 14255)	53
Chapter 76 - Engine Controls			
76-001	03-Oct-03	Engine Controls - Power Control - Introduction of Guard for the Engine Condition Lever	175
Chapter 77 - Engine Indicating			
77-001 Rev. 1	09-Mar-99	Installation of Engine Trend Check System	38
77-002 Rev. 1	18-Jan-02	Engine - Indication - Installation of an Additional Wire.	116
77-003	25-Nov-99	Engine - Indication - Modification to EIS Wiring	104
Chapter 79 - Oil			
79-001	22-Nov-96	Oil Cooler Support Bracket - Replacement	16
79-002	13-Oct-98	Oil Cooler - Modification of the Oil Cooler Shroud	77

≡PILATUS≡
PC12
SERVICE BULLETIN INDEX

- FOCA has issued an Airworthiness Directive against the Service Bulletin
NYI - Service Bulletin not yet issued

SB No.	Issue Date	Title	Ref. No.
79-003 Rev. 1	18-Jun-01	Oil - Oil Cooler - Replacement of the Thermal Actuator on the Oil Cooler	86
79-004 Rev. 1	27-May-02	Engine Oil - Pressure Transducer - Oil Pressure Transducer - Replacement	145
79-005 Rev. 1	21-Aug-03	Oil - Indicating - Introduction of Chip Detector in Engine Accessory Gear Box	141
Chapter 80 - Starting			
80-001	06-Nov-98	Starting - Automatic Start Unit - Installation	78