

≡PILATUS≡
PC12
SERVICE LETTER INDEX

SL No.	Issue Date	Title
001	22-Nov-94	Stick Shaker/Pusher Malfunction Report
002	03-Mar-95	Vendor Service Bulletins
003	06-Mar-95	Nose Landing Gear Exchange
004	22-Mar-95	KSM 375-3 Servo Mounts (P/N: 985.92.03.171/173)
005	20-Sep-95	P&WC Service Bulletin: SB-14230 (Aug 15/95)
006	09-Jan-96	Bendix/King Flight Computer Software Bulletin
007	11-Mar-96	Hartzell Service Letter: HC-SL-61-165
009	27-Jun-96	P&WC Service Bulletin: SB-14230R1
010	27-Jun-96	P&WC Service Bulletin: SB-14233
012	12-Jul-96	Hartzell Alert Service Bulletin: HC-ASB-61-220
013	04-Dec-96	P&WC Service Bulletin: SB-14251R1
014	02-Jun-97	P&WC Service Information Letter: PT6A-034 - Discolored Engine Oil
015	07-May-97	Overview of Fuel Control Unit and Engine Starting Problems
016	23-Jul-97	Hartzell Service Bulletin: HC-SB-61-215, Rev 2 - New Pitch Change Rods
018	02-Jun-97	P&WC Service Bulletin: SB-14246 - Electrical Oil Level Indicator and Oil Level Sight Gage
019	30-Apr-97	LITEF Service Bulletin: 141450-0000-840-004
020	08-May-97	Notification of P/N change for the Fuel Flow Transmitter
021	09-Jul-97	P&WC Service Information Letter: PT6A-035 - Propeller Governor Screw Replacement
022	09-Jul-97	P&WC Service Information Letter: GEN-040 - Lubrication of Nozzle Adapter O-Ring
023	09-Jul-97	Hartzell Service Bulletin: HC-SB-61-225 - Inspect for Broken Pre-load Plate Set Screw
024	09-Jul-97	Hartzell Service Bulletin: HC-SB-61-221 - Introduction of Cylinder Clamp - PC-12 Prior to HJ797
025	10-Jul-97	Hartzell Service Letter: SL-61T - Overhaul Periods and Service Life for Propellers
026	18-Aug-97	Nose Landing Gear P/N Change
028	16-Dec-97	Vickers Service Letters and Service Bulletins: SL-29-920422-01, SL-29-933322-01, SB-920422-29-01, SB-920422-29-03, SB-933322-29-01, SB-933322-29-02 - Electrical Motor-driven Hydraulic Pump Assembly
029	21-Oct-97	P&WC Temporary Revision: TR-79-02 and Service Information Letter: SIL-PT6A-034R1
030	19-Dec-97	P&WC Temporary Revisions: TR-72-17 & 72-18 and Service Information Letter: SIL-PT6A-034R2
031	13-Jan-98	Conversion From Refrigerant R12 (Freon) to Refrigerant R134A in the Vapour-cycle Cooling System
032	01-May-98	P&WC Service Bulletin: SB-14254R1
033	31-Aug-98	Year 2000 Compliance of Electronic Equipment

≡PILATUS≡
PC12
SERVICE LETTER INDEX

SL No.	Issue Date	Title
034	24-Sep-98	PPG Industries Service Information Letter: SIL-172121-001 - Windsheild Strap Repairs
035	19-Jun-98	BFG Service Bulletin: SB-3-1543-32-1
036	28-Sep-98	P&WC Service Information Letter: GEN-PT6-016
037	22-Sep-98	P&WC Service Bulletin and Service Information Letter: SB-PT6A-72-142571 (Commercial Support Program - A98016) and SIL-PT6A-058
038	25-Sep-98	P&WC Service Information Letter: GEN-PT6A-034R4 - Engines - Discolored Oil
040	09-Feb-99	Year 2000 Compliance of Electrical Equipment
041	08-Mar-99	Introduction of P&WC Commercial Support Program Notification- A98030
044	03-Sep-99	Landing-gear Wheel Bearings - Lubrication
045	15-Oct-99	Bendix/King Service Bulletin: SB KCP 220-SW6 - KPC220 Flight Computer Modification
046	20-Apr-00	Fuel Control Unit - Inspection
047	06-Jun-00	Notification of CAWS Control Unit Update and Related Part No. Change
048	23-Jun-00	Introduction of Service Bulletin No. PBA-34-001
049	24-Jul-00	Repair to De-bonded Windsceen
051	17-Jan-01	Improved Baggage Nets
052	20-Oct-00	Generator 2 Drive Belt - Adjustment/Test
053	08-Nov-00	LITEF SB141450-0000-840-009 AHRU Flux valve Excitation Frequency
054	15-Nov-00	Crane Lear Romec SB RG9570-73-002 Engine Driven Fuel Pumps
055	15-Jan-01	Introduction of Typical Wiring Diagram Manual (TWM)
056	21-Dec-00	Inspection of Transducers
057	17-Oct-01	Electrical Power - Modification of NiCd Battery from Aerobatic to Non-aerobatic
058	10-Oct-01	Accessory-Gearbox Oil Seals
059	18-Jun-01	Flap maintenance Adapter Cable
060	18-May-01	Pilatus PC-12 Interactive Technical Publications
061	03-May-01	Landing Gear -Wheel Brakes - Prevention of Frozen Brakes
062	17-May-01	Crane Lear Romec Service Bulletin RG9570-73-002 - Fuel Pump - Replacement of Valve Housing and Related Seals
063	16-Oct-01	Nose Wheel Jack Adapter
064	23-Oct-01	Overhead Panel (Second Battery Option) - Loose Fastener
065	13-Nov-01	Alert Service Bulletin - E-Mail Address and Fax Number
066	21-Nov-01	Main Landing Gear Wheel Fairing
067	08-May-02	LCR 92 AHRS - Calibration Failure of the Magnetic Sensing Unit
068	14-May-02	Wind Vector/Speed and Drift-Angle Bug Display on the EFIS EHSI
069	09-Jul-02	Revision 1 to the Typical Wiring Diagram Manual (TWM)
070	12-Nov-02	Electrical Power - Modification of NICAD Battery from Aerobatic to Non-aerobatic

≡PILATUS≡
PC12
SERVICE LETTER INDEX

SL No.	Issue Date	Title
071	19-Dec-02	Quick Donning Oxygen Mask 957.12.01.206 (Vendor No. MC10-06-121) - Vendor Service Bulletin to improve the microphone quality
072	06-Feb-03	Golan SB 5PC41000_MOD1 (Seat Pan Web - Repair)
073	21-Feb-03	Windshield Repair - Cancellation of Service Letter 049 (PPG SIL 172121-001)
074	24-Mar-03	Pratt & Whitney SIL No. PT6A-116
075	23-Feb-04	Pilots Operating Handbook (POH) - Changes to the Generator 2 Load Outputs
076	08-Feb-04	Pratt & Whitney S.I.L. PT6A-125
077	26-Feb-04	Replacement of Sealant PR1431, Types 1 and 2
078	23-Jun-04	LCR 92 AHRS - Calibration Failure of the Magnetic Sensing Unit
079	12-Jul-04	Inform Operators of Hartzell Service Letter HC-SL-61-236
080	21-Jul-04	Change the Grease Type for Sauter Bachmann Flap Actuators
081	22-Sep-04	Pratt & Whitney SL PT6A-128 FCU Bellows Failure Investigation
082	22-Dec-04	Yaw System AP
083	14-Jan-05	P&WC SL PT6A-131